

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022536**Date Inspected:** 04-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Orthotropic Box Girder (OBG)**Summary of Items Observed:**

On this date Caltrans Office of Structural Material (OSM) Quality Assurance (QA) Inspector, D.Sukanthan was present during the time noted above for observations relative to the work being performed.

This QA Inspector randomly observed the following work in progress:

OBG # BAY 8

This QA inspector received ZPMC notification 08726 to perform Visual Inspection of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector performs random visual inspection of bike path identified as BK004-062.

OBG # CROSSBEAM CB17

This QA observed ZPMC qualified welding personnel identified as 066459 perform Shielded Metal Arc Welding (SMAW) Process repair welding on weld joint CB3001A-017-014. ZPMC Quality Control Personnel (QC) identified as Mr. Li yang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-345-SMAW-2G (2F)-FCM-Repair-1 and Approved Critical Weld Repair B-CWR 2892. See attached photos.

OBG # CROSSBEAM CB18

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG # CROSSBEAM CB19

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG # SEGMENT 12BW

This QA observed ZPMC qualified welding personnel identified as 046709 perform Shielded Metal Arc Welding (SMAW) Process on weld joint CA3012-232. ZPMC Quality Control Personnel (QC) identified as Mr. Wang Liyang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-2213-B-U2-FCM-1.

OBG # SEGMENT 12CW

This QA observed ZPMC qualified welding personnel identified as 057333 perform Shielded Metal Arc Welding (SMAW) Process on weld joint CA3012-233. ZPMC Quality Control Personnel (QC) identified as Mr. Wang Liyang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-2213-B-U2-FCM-1.

This QA observed ZPMC qualified welding personnel identified as 046709 perform Shielded Metal Arc Welding (SMAW) Process on weld joint CA3012-235. ZPMC Quality Control Personnel (QC) identified as Mr. Wang Liyang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2114-FCM-1.

This QA observed ZPMC qualified welding personnel identified as 057333 perform Shielded Metal Arc Welding (SMAW) Process on weld joint CA3012-234. ZPMC Quality Control Personnel (QC) identified as Mr. Wang Liyang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2114-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

As mention above

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-00422372, who represents the Office of Structural Materials for your project.

Inspected By: Sukanthan,Dhanasingh

Quality Assurance Inspector

Reviewed By: Hall,Steven

QA Reviewer